



**DEPARTMENT OF BUILDING SURVEYING  
FACULTY OF ARCHITECTURE, PLANNING AND SURVEYING  
UNIVERSITI TEKNOLOGI MARA**

**QUALITY INSPECTION MANAGEMENT ON CONSTRUCTION SITE**

**This academic project is submitted in partial fulfillment of the  
requirement for the Bachelor Of Building Surveying (Hons.)**

**HAMIZAH BINTI HAIRUM  
(2008283862)**

**APRIL 2010**

## **ABSTRACT**

Inspection on the site is important to control the quality and quantity of work at construction sites. The objectives of this dissertation is to identify the process and method of quality inspection management being held in construction site and highlight the common problem and obstacle during the implementation while identify the solution in preventing the problem or obstacle on carry out the inspection during construction process. There are several differences between the inspection process and method for private projects to government projects. But basically, the same inspection method used in the implementation of quality inspection management on construction site. The commonly problem that occur are about managing the flow of inspection process and the documentation on site. In addition to controlling the quantity and quality on construction sites, inspection can also prevent and reduce disability and serious damage in the future, thus further extending the lifetime of the building. This can also save the cost of building maintenance in the future other than ensure customer satisfaction. Inspection process should be practiced at all construction sites to ensure construction quality produce further developed and developing countries, and quality control.

<p style="text-align: center;"><b>TABLE OF CONTENT</b></p> <p style="text-align: center;"><b><u>QUALITY INSPECTION MANAGEMENT AT CONSTRUCTION SITE</u></b></p>
--

TITLE	PAGES
ACKNOWLEDGEMENT	i
ABSTRACT	ii
CONTENT	iii
LIST OF PHOTOS	ix
LIST OF DIAGRAM	xi
LIST OF TABLE	xi

CHAPTER 1: INTRODUCTION	PAGES
1.1 Introduction	1
1.2 Problem statement	2
1.3 Aims	4
1.4 Scope of study	4
1.5 Objectives	5
1.6 Summary of chapter	5

CHAPTER 2: AN OVERVIEW OF QUALITY INSPECTION MANAGEMENT	PAGES
2.1 What is quality management?	8
2.2 Quality scenario in Malaysia	8
2.3 Introduction of Quality	9
2.3.1 Quality in MS ISO 9000 aspect	10
2.3.2 Four era of quality	10
2.3.3 Development Of Malaysian Standard	10
2.3.4 What is MS ISO 9000	13

2.3.5	Record of testing, inspection and work done on site	23
2.3.6	MS ISO 9001: 2000	23
2.4	What is inspection management on construction site?	42
2.4.1	Introduction	42
2.4.2	Inspection and testing plan	42
2.4.3	Inspection and testing	43
2.4.4	Inspection on construction site	44
2.4.5	Inspection allowed at site	45
2.4.6	Construction level that require inspection	46
2.4.7	Person in charge	50
2.4.8	Equipment use in inspection and testing	52
2.4.9	Inspection, measuring and test equipment	53
2.4.10	Process and method of inspection on site	61
2.4.11	Inspection and testing procedure	66
2.4.12	Inspection advantage and disadvantage	69
2.5	Quality Inspection management	73
2.5.1	Managing the documentation and record of data	73
2.5.2	documentation need	74
2.5.3	documentation benefit	75
2.5.4	process and method of documentation of inspection on site	76

<b>CHAPTER 3: RESEARCH METHODOLOGY</b>		<b>PAGES</b>
3.1	Research Theory/Literature Review	77
3.1.1	primary data	77
3.1.2	secondary data	78
3.2	Flow Chart Of The Methodology	79
3.3	Method Of Data Collection	80

<b>CHAPTER 4: DATA ANALYSIS</b>		<b>PAGES</b>
4.1	Introduction	82
4.2	Government Project	83
4.2.1	Case study 1: Pembinaan Kompleks Perlindungan Sementara Sungai Buloh, Selangor Darul Ehsan.	83
4.2.2	Case study 2: Cadangan membina dan menyiapkan 22 unit rumah berkembar 3 tingkat di no 3, 5, 7, 9, 11, 13, 15, 17, 19, 21, 23, 25, 27, 29, 31, 33, 35, 37, 39, 41, 43 dan 45 di atas Lot No 3, Jalan Kristal 7/67A, dan sebuah pencawang elektrik di Jalan 7/66, Seksyen 7, Shah Alam, Selangor Darul Ehsan untuk tetuan Perbadanan Kemajuan Negeri Selangor (PKNS).	87
4.2.3	Case study 3: Cadangan pembangunan kedai pejabat dan pangsapuri kos sederhana diatas PT 508 HS (D) 107829, Jalan Singa 20/1, Seksyen 20, Shah Alam, Selangor Darul Ehsan secara usahasama diantara Majlis Bandaraya Shah Alam dan tetuan Gandingan Eksklusif Sdn Bhd	91
4.3	Private Project	95
4.3.1	Case study 4: Cadangan pembangunan yang mengandungi 58 unit rumah teres 2 tingkat dan 1 blok gerai 2 tingkat (32 unit), 1 unit pencawang elektrik, 1 unit kebuk sampah di atas tanah kerajaan seluas 4.61 ekar, mukim ampong, daerah hulu langat, selangor darul	95